



No	Phone	Type	Profile	Incoming call accept with device	Outgoing call establish with device	Phone book entries	Call lists			Battery charge level	GSM signal strength	Service Provider	SMS reception	Comments / Version of phone Software used to test
						SIM card	Received calls	Missed calls	Dialled numbers					
1	Nokia	6230i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ V3.30	
2		6310	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ V4.10	
3		6310i	HF	✓	✓	✓	✓	✓	✓	✓	✓		/ V5.60	
4		6230	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 05.24	
5		6233	HF	✓	✓	✓	✓	✓	✓			✓	/ 3.70	
6		6234	HF	✓	✓	✓	✓	✓	✓			✓	/ 3.46	
7		E50	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	/ 06.28.0.0	
8		E60	HF	✓	✓								/ 1.0610.02.15	
9		E70	HF	✓	✓									
10		N70	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	/2.0536.0.2	
11		N73	HF	✓	✓									
12		N91	HF	✓	✓								/1.11.003	
13		N93	HF	✓	✓								/10.0.025	
14		N80-1	HF	✓	✓								/3.0617.0.6	
15		8910	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/04.02.25	
16		6822a	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ V4.52 19-05-05 RM-69	
17		6021	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ V 04.50	
18		6670	HF	✓	✓					✓	✓	✓	/ V 6.522.0	
19		6680	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	V2.04.15	
20		6681	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	/ V 3.10.6	
21		6630	HF	✓	✓					✓	✓	✓	/2.39.152	
22		9300	HF	✓	✓					✓	✓	✓	/V 5.22	
23		9300i	HF	✓	✓					✓	✓	✓	/V5.50	
24		6270	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/V03.66	
25		6103	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/V04.90	
26		6682	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	/V3.01.1	
27		7280	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		
28		7710	HF	✓	✓					✓	✓	✓	/V3.04.2	
29		8800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/V3.60	
30		6280	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/V3.60	
31		6288	HF	✓	✓	✓	✓	✓	✓			✓	/ V5.92	
32		6600	HF	✓	✓					✓	✓	✓	/V3.42.1	
33		5500	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	V 03.18	
34		6125	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	V 03.71	
35		6111	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/V03.58	
36		6151	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/V3.56	
37		6131	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/V3.70	

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working

✓* Phonebook entries only from phone (with installed Applet)



No	Phone	Type	Profile	Incoming call accept with device	Outgoing call establish with device	Phone book entries	Call lists			Battery charge level	GSM signal strength	Service Provider	SMS reception	Comments / Version of phone Software used to test
						SIM card	Received calls	Missed calls	Dialled numbers					
38	Motorola	V500	HF	✓	✓					✓	✓	✓	✓	/ TRIPLETS_G_08.09.1DR_VA
39		V550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.26R
40		V551	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R47_G_08.17.0FR_01
41		V557	HF	✓	✓					✓		✓		/R4512_G_08.28.40R
42		V635	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R474_G_08.48.24R_A
43		V620	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.66.0BR
44		ROKR E1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R373_G_0E.30.42R
45		L2	HF	✓	✓					✓		✓		/ R3511_G_0A.53.15R
46		L6	HF	✓	✓					✓		✓		/ R3511_G_0A.52.26R
47		L7	HF	✓	✓	✓	✓	✓	✓	✓		✓	✓	/ R4513_G_08.B7.54R-RB
48		V3	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R374_G_0E.40.79R
49		V3i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R479_G_08.B4.85R
50		K1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/R4527_G08.22.07R
51		U6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R478_G_08.83.76R_A
52		C390	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R368_G_0B.A0.0FR
53		E1000	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R478.G_08.83.76R_A
54		Z3	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/R4527_G08.01.02R
55		Sony Ericsson	K610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	
56	K700i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R2L001 prgCXC 125821_EU_1_C
57	S700i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3C002 PRGCXC125936_EU_2_T
58	D750i		HF	✓	✓	✓	✓	✓	✓	✓	✓			/ SW:R1J002 PRG CXC125952_EU_1_CLR1J002
59	V800		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: R1J002 PRG CXC 125839_EU_1_VA
60	W550i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: R4BA041
61	W600i		HF	✓	✓					✓	✓	✓		/ SW:R7B046
62	W800i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ SW:R1L002 PRG CXC1250092_EU_1_CA R1L002
63	W810i		HF	✓	✓	✓	✓	✓	✓	✓			✓	
64	W850i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:R1ED001 PRGCXC1250201_Vodafone_CYR1E
65	W900i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ SW: R5BC004
66	W950i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		
67	P990i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ CXC162058R4F01
68	V630i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ SW: R1CE001
69	V800		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
70	K750i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R1N035 prgCXC 125952_EU_1_CL
71	K800i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R1AA049 prg CXC1250210
72	T610i		HF	✓	✓					✓	✓	✓		/ R3C002
73	T630i		HF	✓	✓					✓	✓	✓		/ R7A011
74	K600i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2AC001 CXC1250076.EU.6_MI
75	K510i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4CH003 1250231_GENERIC_C0
76	Z600		HF	✓	✓	✓	✓	✓	✓	✓	✓		✓	
77	Z1010		HF	✓	✓	✓	✓	✓	✓	✓	✓			/ R1G007 PRG CXC125432_EU_1_V



No	Phone	Type	Profile	Incoming call accept with device	Outgoing call establish with device	Phone book entries	Call lists			Battery charge level	GSM signal strength	Service Provider	SMS reception	Comments / Version of phone Software used to test
						SIM card	Received calls	Missed calls	Dialled numbers					
78	Siemens	CX75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:05	
79		S65v	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:25	
80		SK65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:46	
81		S65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 25	
82		SP 65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 47	
83		M75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:05	
84		S55	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:16	
85		BenQ M81	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:46	
86		BenQ S68	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		
87	Samsung	E720	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 1.0g	
88		D600	HF	✓	✓									
89		D800	HF	✓	✓	✓	✓	✓	✓		✓	✓	/ SW: 1.1	
90		E900	HF	✓	✓	✓	✓	✓	✓		✓	✓	/ SW: 1.0a	
91		D900	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ D900E.05	
92		D307	HF	✓	✓								/ SW:06	
93		D357	HF	✓	✓	✓	✓	✓	✓		✓	✓	/ SW: 1.4	
94	BlackBerry	7100	HF	✓	✓								/ SW:4.02.16	
95		7130	HF	✓	✓								/ SW:4.10.327	
96		8100	HF	✓	✓								/ SW: 4.2.0.64	
97	LG	KG800	HF	✓	✓									
98		KG810	HF	✓	✓									

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working

✓* (with installed Applet)

Phonebook entries only from phone (with installed Applet)